




1930's to 1950



**1951 & 1952**



**1953 onwards**



## **Oil Leakage from Front Chaincase**

A new type of rubber chaincase-band is now available which is mushroom in section, with a narrow and a wide groove for both the front and rear portions of the chaincase. Where persistent oil leaks occur from this part of the machine, the new type rubber case will provide the remedy.