

56/2



SERVICE BULLETIN AND TECHNICAL DATA

SPARES PRICES

Spare Parts invoiced on and after 1st September 1956, will show a further surcharge of 10%.

INSTRUCTION BOOK ERRATA

Carburettor settings shown in the 1956, 600 cc. Twin Instruction Book, were taken from the prototype. The correct main jet size for this Model is 260, (250 with air cleaner). Needle position centre notch.

SPARES LIST ERRATA (PRINTERS ERROR)

1956 Matchless Single Cylinder List, Page 5.

Piston Complete 018927 should read £2: 7: 8d.

1956 A. J. S. Single Cylinder List, Page 13.

Silencer 021887 should read - £2: 7: 4d.

MASTER SPARES LIST

Supplements for the 1956 Models will be available Shortly. Copies can be obtained on demand.

* * * *

August, 1956.
FWN/DD.

Issued by:

ASSOCIATED MOTOR CYCLES LTD • LONDON S.E.18
MANUFACTURERS OF A.J.S. AND MATCHLESS MOTORCYCLES